

## 1920's Vintage ATCO Heat Indicator Temperature Steam Boiler/Wood Stove Checklist of E/OHS Activities for Indoor Air Quality

Program Contact Person: Tim Spencer

Is the IAQ Plan in place? **Yes** No

Is the Plan current? **Yes** No

Has the Plan been reviewed this school year? **Yes** No

Has an IAQ Committee been established? **No**

Has the annual cursory walk-through been conducted? **Yes** No

Have the key building systems been evaluated? Yes **No**

When was the evaluation completed? N/A

Who conducted the evaluation? N/A

Were occupied areas of the district evaluated using the EPA's Tools For Schools check list or equivalent?

- Teachers check list? An information fact sheet was provided all -staff.  
# of forms distributed                      # of Forms returned:

- Building maintenance checklist? \_\_\_\_\_

- Building ventilation checklist? \_\_\_\_\_

Training conducted \_\_\_\_\_  
(date)

Training has been scheduled for \_\_\_\_\_.  
(date)

Has the District determined the mechanical ventilation rate of each occupied space?  
Yes **No.**

Supportive technical services were conducted on: N/A\_\_\_\_\_.  
(date)

Results of technical services are located? N/A\_\_\_\_\_

## IAQ Survey Review Form

### St. Mary's Catholic School Worthington

Building: Elementary School

Building Contact: Jackie Probst

Program Contact: Brian Parrie

Room Identification Contact individual	Water Intrusion	Ventilation problems	Building failures i.e. foundation or roof problems	Cleanliness/ Proper storage	O&M Carpets

Recommendations: No official complaints during school year. Issues exist for ventilation. Unit vents provide some fresh air to the second and third floor classrooms. The basement classrooms receive fresh air only by opening windows..

Walk-through conducted by: Brian Parrie Date: 2/6/2017

Note: